

Nº 3697

Place Hingham, Massachusetts.

Date of Completion.....

Building Saint John's Church.

Persons Interested.....

Price: \$480, not incl. scaffolding. Later work extra.

Grofit 22% 106.21

Minister.....

Denomination.....

Edgar T.P. Walker, Architect, 131 State Street, Boston 9, Massachusetts.
Architect.....

Vents.....

Position in Church Side chancel windows.

Height from floor.....

Protection Glass.....

Groove 3/4" Metal
Rabbet groove Stone
Wood Stone.

Exposure.....

Footage.....

Inscription.....

Design wanted.....

Staging.....

Templates.....

Blueprints.....

General Information..... Templates for Architect. Removing the windows and reinstalling them at a later date in the new tracery windows in the proposed new chancel.

New stone frames to be made by Emerson and Norris.

See information in folder about trains and busses to Hingham.

Contract states:

Architect states: "Remove from present limestone tracery windows in sanctuary, the two Vinton Memorials, and reinstall in the corresponding locations in the new stone tracery window frames of the new sanctuary at a later date. This work to be done under the direction of the architect, and at a time best suited to the conditions of construction at the building, to be determined by the general contractor and the architect. This work to be complete in every detail. The leadwork in all sections to fit the rebates of the tracery work, all of which is shown in our full size details of these windows. This work does not include furnishing scaffolding, which will be furnished under a further expense by the owner. Contractor is responsible for all necessary repairs of any damage occurring during operation."

Later December 17, 1954 - Mr. Walker telephoned. They are going to build a new building just outside one of the windows, and they have asked us to move the one at the left - next to the chancel, store it here, and reinstall it later. - Week of December 20th to remove - install after work is completed at the site.

6/7/55 - Mr. Walker phoned
Stuers bid \$500 + 600 for removing &
reinstalling it.