

See sheet #137 for balance of this window.

CHARLES J. CONNICK : DESIGNER AND WORKER IN STAINED AND LEADED GLASS : NINE HARCOURT STREET, BOSTON, MASSACHUSETTS

City or Town Spokane State Wash. No. 1717
Date of June 15, 1955.
Church Saint John the Evangelist Cathedral Completion Try to have in place for Aug. 13, 1955, for Miss Jewett's wedding.
Donor and Address
Architect Whitehouse and Price, Spokane. Quality of \$12,000 entire rose. Glass Central portion made for \$2500; Cost of remainder \$9500
Denomination Episcopal. Dean McAllister. Rt. Rev. Russell (\$37.)
and Minister Rt. Rev. Edward M. Gross, S.T.D. Bishop of Spokane. Rt. Rev. Russell (\$37.)
Sturgis Hubbard (Formerly Suffragan of Michigan). sight
Footage 295-9-0 in entire window (40' now in place) Sizes, full Profit - 30% 2907.38

Ventilators Set by
Position in Church Rose in West End Over entrance.
Height from floor 31' Protection Glass No. Groove Rabbet Stone Work
Points of compass
Quality of light West. "Keep in mind that we have a strong western sun for a great many months of the year, and I presume you will keep your window quite dense in its colors". Whitehouse Jan. 9, 1933.
Inscription

Design wanted Staging
Shipping address Blue-prints Received Yes.
Bill to Templets Yes.
Photos of Cartoons Mailed

General Information The price of the entire window is \$9000. (\$30.40 per ft.). The price of the section now in place was \$2500, including cost of templates and installation. (This job Number was #1371).

Central part is installed, - including the central member; the 12 small triangular pieces immediately surrounding it, the six larger members around these, and the doves in the petals between these six.
C.J.C. wrote: "Our intention was to use small pieces of glass throughout the window, even though the design may not make this fact clear". to Whitehouse 1/14/33
C.J.C. wrote Whitehouse Jan. 30, 1933 - "When we come to the bronze struts I think we can do just as you suggest, supplying wide sheaves at the edge of the glass to go around both sides of these bars. If they are securely fastened, they should not leak."
Jan. 16, 1933 - C.J.C. said, "I think that the color ought to be improved (on the sketch), especially the blues. Think that the design should be restudied before

For addresses of those to be notified as window progresses, see other side.

the window is made, especially through the star and cloud forms in the shapes just beyond the doves.