



We would use three-sixteenths inch rough plate for these repairs if it did not look too different from the rest of the glass. Otherwise, we may have to use ordinary double strength window glass to make it correspond.

To replace the five broken protection windows in the sacristics (including the one on the northeast side), would cost eighty dollars, and we estimate the cost of repairing the four broken leaded glass windows in the sacristy about \$125.00.

The repairs in the tower, working from your scaffolding at the front window and from a ladder at the side window, are estimated at seventy-five dollars.

The cost of removing the protection and leaded glass from the great chancel window, adding leads to the narrow lancets, and putting both the leaded glass and new one-quarter inch rough plate protection glass back in the frames - after they are strengthened - we would estimate at four hundred and fifty dollars, working from your scaffolding inside and outside.

There are four broken pieces in the aisle windows which we could replace for a cost of about \$20.00.

Grand total of \$925.00 plus Phillips other costs." "These are estimates, and we believe it should be possible to do the work for these amounts. If there is a saving, give the benefit to the church.