

To reach the Church, take route 128 to 3: then 129 goes right past the church.

Nº 4510

Place Chelmsford, Massachusetts.

Building All Saints Church, Billerica Road.

Date of Completion July 16, 1962.

Persons Interested Donor: Mr. Clayton.

Price: \$2340 (\$37.14). * *

Loss 21% \$ 499.00

Minister The Reverend P. D. Twelves, Robinson (or Robertson), Davis and Potter. (Formerly with Coolidge, Shepley, etc.).
Architect.....

Denomination Episcopal

Vents.....

Position in Church Big window opposite the chancel.

| | | | |
|----------------------------|-----------------------------|---------------|------------------|
| Height from floor 20 feet. | Protection In place.* Glass | Groove Rabbet | Metal Stone Wood |
|----------------------------|-----------------------------|---------------|------------------|

Exposure South..... Footage 63 feet.

Inscription.....

Design wanted soon About Oct. 11,..... Staging.....

Templates..... Blueprints.....

General Information This is a new rather modernistic church. At present this window is divided into 14 narrow panels by vertical mullions $3\frac{1}{2}$ inches wide. Half of these are just set in inside the present glass, which is practically white rough-textured Marine antique. These could come out, leaving 7 panels. They are putting in an organ at either side and at the base. Pipes will come up in front of the window, probably about 3 feet at the sides, going down to perhaps a foot and a half at the center, forming a sort of curved V-shape. Color will show through between the pipes.

To have a great figure of the Welcoming Christ, with hands extended through the lancets. A golden radiance back of Him something like the Miami Beach balcony window, and perhaps just a very faint suggestion of a cross, made by the central figure and accented rays at either side.

A background going into fairly deep blues, around, above and below, with some suggestion of rays throughout from the figure, and possibly simple symbols of four Evangelists in the four corners of the blue fields.

*We could set the glass right in the frames inside the protection glass, with just a narrow lead around the outside of the sections.

Price includes installation, but not carpentry work involved in the installation. We think the extra vertical divisions will come out quite easily, but we may need small moldings to hold the glass in place. Question whether it should go toward the outside or toward inside. The space seems to be about 6 inches deep, and looks like a smooth*