

Gardner Mission
Episcopal Church -
Repair Job.

809

See 794 for Channel
" 808 for aisle

Repair all aisle windows, reglazing where necessary, and inserting new pieces where necessary including the tracery for the left aisle windows nearest the Channel to conform with the tracery of the other windows now in place.

Four top fall in oculatoids approximately 30" high and the full width of the channel. They are to be placed in the bottom of the centre lancet of each of the four windows and are to conform with the two oculatoids to be placed in the centre lancets of the two aisle windows nearest the Channel.