

No 3940

Place Seattle, Washington.

Building Church of the Epiphany, 1805 Thirty-Eighth Av., Seattle 22 (At East Dennyway).

Date of Completion September 1, 1962.

Price: \$1400 (\$41.17).
\$1800 (\$47.06)

Persons Interested.....

Loss 21% 367.00

Minister The Rev. Elmer Christie

Denomination Episcopal.

Architect Whitehouse, Price, DeNeff and Deeble, Hutton Building, Spokane, Wash.

Vents NOTE: VENTS, BARS AND T-BARS IN PLACE. See important note about vent Size below*

Position in Church Nave ~~#2~~ ^{2nd} from chancel on ~~South~~ Side.

Height from floor 4' 30"

Protection Glass

Groove Rabbet

Metal Stone Wood

Exposure ~~South~~ North

Footage 34 feet.

Inscription None

Design wanted SOON.

Staging

Templates Yes.

Blueprints

General Information See floor plan on #3849, also windows in place.

The Baptism of Our Lord.

Marlowe writes: "Please don't solder joints, just tack them on kites and 1 ear on upper section; had to chisel in for upper bar, but I suppose it had to be so, almost into the cusp. Wires 2 inches down too far. This was written after setting the Sermon on the Mount.

The 8th window, or the one nearest the main entrance to the nave is partially covered by the balcony. Only about 2/7 of the window is visible below the balcony and about the same space including the stone tracery above the balcony. This will have to have a special treatment, so keep this in mind as we develop the typical design for the group, so that the parts which do show will be in harmony with the others.

*Important, re: vent. Marlowe writes Oct. 1960 "...too much to cut off. Exact vent size 25 3/8 x 28 1/4. It has a 1/8" reveal all around...." Note given to glaziers.

*OK check color
re: how to
protect when
designing*

The three remaining aisle windows...
As planned, they are devoted to the Baptism
of Our Lord by Saint John the Baptist, the
First Miracle at the Wedding Feast of Cana,
and The Resurrection of Our Lord.

Related texts are indicated on the open books
below. These, of course, can be changed to
others that you may prefer...."

IMPORTANT: Marlowe writes, October 3, 1960 - "As ~~the~~ stone lead is not used, tack
the kites and left ear of the top section to take apart for installation."