

Nº 3921

Place Bronxville, New York.

Building The Reformed Church, Pondfield Road and Midland Avenue. TEL. Dierfield 7-6776 Date of Completion.....

Persons Interested Contractor for alterations to chancel: Mr. Peter N. Barr, of Barr, Gleason and Barr, Inc., 501 Fifth Avenue, New York 17.

Minister Lowell Russell Ditzen, D.D. Rector. Price: \$1000 ? (10/31/56). Denomination Dutch Reformed

Architect Eggers and Higgins, New York, Architects for alterations to chancel.

Vents..... *Billed at Cost \$ 2139.50*

Position in Church Chancel Window.

Height from floor..... Protection Glass..... Groove Rabbet..... Metal Stone Wood.....

Exposure..... Footage.....

Inscription.....
.....
.....

Design wanted..... Staging.....

Templates..... Blueprints.....

General Information Remove chancel window, repair any breaks, and re-install after chancel is altered.

Glass removed and packed to be sent to us by Mr. William J. Durhan, of George Durhan and Son, 115 East 18th Street, New York 3, New York. Their bill for this part of the work is \$317.39.

The window was insured for \$3200.00.

.....
.....
.....
.....
.....
.....
.....
.....