

Nº 3790

Place Stockton, California

Building First Presbyterian Church

Date of Completion June 1, 1956

Persons Interested Miss Jeannette Whiting, 227

Price \$675. (\$75.) for several at one time.

West Willow Street, Stockton. Mrs. Howard Lenz, 1903 Sheridan Way, Lincoln Village, Stockton, Cal.

Minister

Denomination Presbyterian

Architect

Loss. 94.96 = 14 7/10

Vents

Position in Church South aisle window, second from transept

Height from floor 4 feet

Protection Glass

Groove Rabbet

Metal Stone Wood

Exposure South

Footage 9 feet

Inscription (Not yet received) "In memory of Alice Thompson Minor and Caroline Minor Goodwin - by Caroline Goodwin Gwerder and Alice Goodwin Lenz."

Design wanted

Staging

Last wd. installed by Karl Schmitt of Stockton.

Templates

Blueprints

General Information Lower medallion: Presentation in the Temple; upper medallion, Flight into Egypt. (RED MEDALLIONS).

Minimize the halo as much as possible, BE SURE GLASS IS BROKEN UP WITH NO LARGER PLAIN PIECES. RICH COLOR. NO BRICK OR TERRA COTTAS. Mrs. Lenz likes rich blue and red.