

Fell

CHARLES J. CONNICK : DESIGNER AND WORKER IN STAINED AND
LEADED GLASS : NINE HARCOURT STREET, BOSTON, MASSACHUSETTS

City or Town Milford, State Mass. No. 1799

Church Saint Mary's Church (Roman Catholic) Date of Completion December 1934.

Donor and Address

Architect Mr. Phillips of Maginnis & Walsh, in charge. Quality of Glass * 4500.
Roman Catholic. 7500.

Denomination Roman Catholic. and Minister Rev. Jeremiah A. Riordan. 3000.

Footage sight Sizes, full

Ventilators Set by

Position in Church

Height from floor Protec- Groove Stone
tion Glass Rabbet Wood

Points of compass
Quality of light

Inscription

Design wanted Staging

Shipping address Blue-prints
Received

.....

Bill to Templets

Photos of Cartoons Mailed

Donald Wells in charge of work there for us.
General Information Tower windows broken - see what can be done there.

Report of Saturday 29, 1934. Found big holes in two windows in the tower. One lower inside - other in the large window high up. This large window, around forty feet from the floor, has eight main lancets in two tiers with considerable tracery above. The lancets are about two feet wide and around twelve feet high, in quarries of four and one-fourth by seven. It is thought that glass can be taken from the opposite window, which is boarded up, to repair the hole. Then there are four lancets in the front, and four in the back in pairs. Each is about two feet wide by sixteen feet high. This marks a total of somewhere around 460 square feet.

Told Phillips that if they would put up the scaffolding with necessary footings to reach the outside of the windows, we would undertake to repair * the glass and put in the essential Tees and bars for between three hundred

For addresses of those to be notified as window progresses, see other side.

10

and five hundred dollars.

There is also a window broken out in the lower part of the tower in the vestibule. This should probably be repaired at the same time, and included in our total price.